



राष्ट्रीय फैशन प्रौद्योगिकी संस्थान, मुंबई

Plot No. 15, Sector 4, Kharghar, Navi Mumbai - 410210

Ref. No. 4750/Bldg/Extra Work/ 2015

Date: 28.06.2019

To,

Sub: Internal Repairing and Carpentry Work at NIFT Campus Plot No. 15 & Plot No.20, Sector - 4, Kharghar, Navi Mumbai - 410210.

Sir,

NIFT- Mumbai invites quotation for "Internal Repairing and Carpentry Work at NIFT Campus Plot No. 15. Sector - 4, Kharghar, Navi Mumbai-410210." The scope of work and the detailed specification are mentioned below.

Sl. No.	Work Description	Qty Nos.	Location	Dept.	Rate in Rs,	Amount in Rs.
1	Main Door Handle	1	306	TD		
2	Faculty Chair	2	310	TD		
3	Students Chair	3	308	TD		
4	File Cabinet need to be repair	1	442	FMS		
5	Cupboard Handle and Lock to be repaired	1	442	FMS		
6	Black Chair	1	442	FMS		
7	Red Chair for Repair	1	442	FMS		
8	Wooden Chair	1	435	FMS		
9	Key Board Stand	1	431	FMS		
10	Wooden Cupboard	5	435 A	FMS		
11	Wooden student Locker handle	1	Passage	FMS		
12	Lock required in Room No. 435 A	1	435 A	FMS		
13	Computer Table	2	202	FP		
14	Blue Chair	9	202	FP		
15	Student Chair	5	302	FP		
16	Student Table	1	303	FP		

17	Student Chair	6	304	FP		
18	Student Chair	1	312	FP		
19	Door Closer	1	312	FP		
20	Door Handle	1	313	FP		
21	Door handel	1	Lift side room	AD		
22	Door handel	1	346	AD		
23	Cabin Glass		AD Workshop	AD		
24	Door stopper broken	141	Annex-I	Girls Hostel		
25	Window net broken	68	Annex-I	Girls Hostel		
26	Curtain rod holder broken	5	Annex-I	Girls Hostel		
27	Door latch fixing	78	Annex-I	Girls Hostel		
28	Glass broken	6	Annex-I	Girls Hostel		
29	Mirror fitting	2	Annex-I	Girls Hostel		
30	Study table sunmica crack	2	Annex-I	Girls Hostel		
31	Kadappa patti work	2	Annex-I	Girls Hostel		
32	Main door frame crack	14	Annex-I	Girls Hostel		
33	Dressing table sunmica crack	11	Annex-I	Girls Hostel		
34	Study table fitting	66	Annex-I	Girls Hostel		
35	Door Repairing	14	Annex-I	Girls Hostel		
36	Table repairing sunmica work	1	311	FD		
37	Marble work of sitting table	1	Entry of AB-II	Entry of AB-II		
38	Door Lock	1	215	CAC		
39	Table compartment repairing	1	215	CAC		
40	Glass Door Repairing Bottom Wooden	1	Faculty Room	M.Des		
41	Cupboard Handle repairing	1	Assistant Cabin	M.Des		
42	Cupboard lock replacing	1	208	BFT		

Terms & Conditions

- 1) Rate should be quoted inclusive of all taxes and labour, Transportation charges etc.
- 2) Quotation should be signed & should be each on or before 05.07.2019
- 3) Any damage items shall have to be replaced by the Contractor at his own cost.
- 4) Supply and installation of each and every material should be in requisite specifications.
- 5) Payment will be released after successful completion of the work as per requirement of user Department and after the satisfactory

Address:

National Institute Of Fashion Technology
Plot No. 15, Sector 4,
Kharghar,
Navi Mumbai - 410210


Joint Director
NIFT Mumbai